



The State of Utah

Department of
Natural Resources

Division of
Oil, Gas & Mining

ROBERT L. MORGAN
Executive Director

LOWELL P. BRAXTON
Division Director

OLENE S. WALKER
Governor

GAYLE F. McKEACHNIE
Lieutenant Governor

Representatives Present During the Inspection:

OGM Kit Pappas Environmental Coordinator

OGM Steve Demczak Environmental Scientist III

Inspection Report

Permit Number:	C0070020
Inspection Type:	COMPLETE
Inspection Date:	Thursday, June 10, 2004
Start Date/Time:	6/10/2004 10:00:00 AM
End Date/Time:	6/10/2004 3:00:00 PM
Last Inspection:	Friday, May 21, 2004

Inspector: Steve Demczak, Environmental Scientist III

Weather: Raining, 50 Degrees

InspectionID Report Number: 297

Accepted by: pgrubaug

7/13/2004

Permitee: **HIDDEN SPLENDOR RESOURCES INC**

Operator: **HIDDEN SPLENDOR RESOURCES INC**

Site: **HORIZON MINE**

Address: **HC 35 BOX 370, HELPER UT 84526**

County: **CARBON**

Permit Type: **PERMANENT COAL PROGRAM**

Permit Status: **ACTIVE**

Current Acreages

1,998.99	Total Permitted
9.50	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

- ☒ Federal
☐ State
☐ County
☒ Fee
☐ Other

Types of Operations

- ☒ Underground
☐ Surface
☐ Loadout
☐ Processing
☐ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Permit Condition #2 states that Hidden Splendor Resources, Inc will update the appropriate sections of the mining and reclamation plan with the permit transfer information by August 1, 2003. The first submittal was on September 30, 2003, task #1747 and was found to be deficient. This second submittal from Hidden Splendor has a new task #1836. The Division has approved amendment #1836.

No violations.

Inspector's Signature

Steve Demczak
Steve Demczak, Environmental Scientist III

Inspector ID Number: 39

Date

Friday, June 11, 2004

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801
 telephone (801) 538-5340 facsimile (801) 359-3940 TTY (801) 538-7223 www.ogm.utah.gov

Utah!
Where ideas connect™

Permit Number: C0070020
 Inspection Type: COMPLETE
 Inspection Date: Thursday, June 10, 2004

Inspection Continuation Sheet

Page 2 of 4

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

2. Signs and Markers

The identification sign was inspected and complied with the requirements of the R645 Coal Rules.

3. Topsoil

The topsoil pile was inspected with no signs of wind or water erosion. Vegetation is growing on the topsoil pile.

4.a Hydrologic Balance: Diversions

The diversions were spot-checked and were functioning as designed. No water was flowing within the diversion. The outside weather conditions was slightly raining during the inspection.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The sediment pond did contain water but was not discharging during the inspection. No hazardous conditions were noticed during the inspection. The sediment pond was inspected by the permittee on April 13, 2004 for the second quarter.

4.c Hydrologic Balance: Other Sediment Control Measures

The silt fence within the roadside diversion need repair. The fence was functioning as designed but the upper part of the fence was hanging down. Permittee has committed in repairing the silt fence.

4.d Hydrologic Balance: Water Monitoring

The permittee will be taking water samples for the second quarter on June 18th. The permittee has entered the first quarter water data into the Division's database system.

4.e Hydrologic Balance: Effluent Limitations

The permittee was in compliance with the UPDES permit for May of 2004.

7. Coal Mine Waste, Refuse Piles, Impoundments

Horizon has no refuse pile.

8. Noncoal Waste

The mine site was picked up of non-coal waste material.

14. Subsidence Control

This information is in the annual report.

18. Support Facilities, Utility Installations

No new support facilities were constructed since the last inspection.

Permit Number: C0070020
Inspection Type: COMPLETE
Inspection Date: Thursday, June 10, 2004

Inspection Continuation Sheet

Page 4 of 4

19. AVS Check

The Mining and Reclamation agreement has the same information as the Applicant Violator System.

20. Air Quality Permit

The air quality permit is DAQE-700-00.

21. Bonding and Insurance

The insurance will expire on June 1, 2005.